

Affected Products – RAC15-SK and RAC20-SK AC/DC Converters

Dear customers and distributors, we herewith inform you about a product change in the following products:

Art #	Recom Products	Art #	Recom Products
20001195	RAC20-05SK/W	20001167	RAC20-05SK
20001182	RAC15-05SK		

Please note that due to an error, the isolation withstand voltage was given as 4kVAC instead of 3kVAC in the original datasheets. This error has been corrected. Please ensure that any local or cached copies of the original datasheet have been replaced with the corrected version. There has been no change to the converter itself.



Issue Date: 24 March 2019

Steve Roberts
Technical Director
RECOM Engineering, Gmunden,
Austria

For further information, please contact our sales teams:

Europe: Tel: +49 (0) 6102-88381-0 or info@recom-electronic.com
Asia: Tel: +65 62768795 or enquiry@recom-power.com
North-America: Tel: +1-720-386-0400 or admin@recom-power.com